M. A. R. 57 (Rule 116)
Measurement Book

No. E 483510

Serial No. 1st & final

Name of work ..... From ..... To .....

Name of Contractor of nature of Agency..... Sri. D.V. Kumar .....

Date of commencement of work.....

Date	Full description, etc, of work	Dimensions				Contents	Reference to last Measurement
		Number	Length	Breadth	Depth		
1	2	3	4	5	6	7	8
	Name of Work: Providing water Supply lines and other works in Chikkasandra and Shettyhalli in W.No.12, Shettyhalli Sub-division.						
	Estimated Cost: Rs. 30.00 Lakhs.						
	Job No: 012-19-000018.						
	Work order No: No. EE/DD/ WO/14/2021-22 dt: 09.06.2021						
	Executed SN. 16/7/2021						

Scanned by CamScanner

"ABSTRACT"

Date 1	Full description, etc, of work 2	Dimensions: Number 3	Length 4	Breadth 5	Depth 6	Contents 7	Reference to last Measurement 8
Sl. No.	Description of work.	unit	Qty	Rate		Amount.	
1.	Earthwork Excavation	Cum	4265.78	211.00		900079.58	
2.	providing 63 mm pvc pipe	Rmt	5589=00	107=00		589463=00	
3.	Refilling available Earth	Cum	4265.78	120=00		511893.60	
4.	10 cm thick precast slab	Sqm	220=00	1200=00		264000=00	
5.	250 mm thick precast slab	Sqm	30=00	3000=00		90000=00	29560.
6.	Removing & Resetting of foot path slab.	Sqm	1368=00	208=00		284544=00	
				TOTAL =		2639980.18	
		GST charges		12% =		316797.62	
		GRAND TOTAL			=Rs.	2956777.80	

Checked 16/7/2021

Correct

Assistant Executive Engineer
Shettyhalli Sub-Division

Scanned by CamScanner

Audited and admitted for Rs. 2955165=00

Passed by Cheque for Rs. 2750331=00

Twenty Seven Lakhs Fifty Thousand Three hundred and Thirty one only

M. A. R. 57 (Rule 116)

Measurement Book

No. E 483511

Serial No. .....

Name of work ..... From ..... To .....

Name of Contractor of nature of Agency 204834=00

Date of commencement of work .....

Date	Particulars of Description, etc. of work	Number	Dimensions: Length	Dimensions: Breadth	Dimensions: Depth	Contents	Reference to last Measurement
1	2	3	4	5	6	7	8
	B.B.M.P. Dasarahalli Division						

Certificate

1. Certified that the Contractor has work done satisfactorily
2. The Contractor has removed the debries from work site.
3. There is no departmental issued to Contractor.

Executed
16/7/2024

[CONTRACTOR]

Assistant Executive Engineer
Shettyhalli Sub -Division

Scanned by CamScanner